

1/22

FIG.1




FIG.2A




FIG.2B




FIG.3A





FIG.3B



2/22

FIG.4A




FIG.4B




DIAGRAM IN THE DIRECTION OF ARROW A (TOP PLAN DIAGRAM)

3/22

FIG.5A





FIG.5B



4/22

FIG.6A





FIG.6B







DIAGRAM IN THE DIRECTION OF ARROW B (TOP PLAN DIAGRAM)

6/22

FIG.8A




FIG.8B




FIG.8C





FIG.9



7/22

FIG.10





FIG.11



8/22

FIG.12





FIG.13

MASS CHANGE WHEN A ROLLER
MATERIAL IS SOAKED IN DEVELOPER



9/22

FIG.14






FIG.15




PARTIALLY ENLARGED DIAGRAM



11/22

FIG.18



12/22

FIG.19A





FIG.19B



13/22

FIG.20





FIG.21



14/22

FIG.22






FIG.23




15/22

FIG.24




16/22

FIG.25




17/22

FIG.26



18/22

FIG.27



19/22

FIG.28




FIG.29A






FIG.29B



20/22

FIG.30



21/22

FIG.31A




FIG.31B





FIG.32



22/22

FIG.33

